



NOTE:  
SEE SHEET 2 FOR MATERIAL LIST

LINE#	QTY	DESCRIPTION	UNIT	ANGLES
D	1	REPAIR PARTS BULL. 5110 & 5210		
C	1	NEMA SIZE 5A, 400 AMP CONTACTOR		
B	1	MOLDED BASE & FABRICATED ARMATURE		
A	1	MODEL 2001		

  

LINE#	QTY	DESCRIPTION	UNIT	ANGLES
D	1	REPAIR PARTS BULL. 5110 & 5210		
C	1	NEMA SIZE 5A, 400 AMP CONTACTOR		
B	1	MOLDED BASE & FABRICATED ARMATURE		
A	1	MODEL 2001		

  

LINE#	QTY	DESCRIPTION	UNIT	ANGLES
D	1	REPAIR PARTS BULL. 5110 & 5210		
C	1	NEMA SIZE 5A, 400 AMP CONTACTOR		
B	1	MOLDED BASE & FABRICATED ARMATURE		
A	1	MODEL 2001		

  

LINE#	QTY	DESCRIPTION	UNIT	ANGLES
D	1	REPAIR PARTS BULL. 5110 & 5210		
C	1	NEMA SIZE 5A, 400 AMP CONTACTOR		
B	1	MOLDED BASE & FABRICATED ARMATURE		
A	1	MODEL 2001		

DATE: 11-18-03 DR: LHM  
 1 OF 2  
 11 10 9 8 7 6 5 4 3 2 1